

KING'S LYNN CONSERVANCY BOARD.



Notice to Mariners No. 09 / 2022

East Coast of England - The Wash

Approaches to the Wash

Roaring Middle Light Float re-established on station

Mariners are advised that on 20th April 2022 the Roaring Middle light float was re-established at position, 52° 58.640' N 00° 21.080' E, and the temporary Safe Water Mark can light buoy was removed

Please contact the Harbour Office for further information.

NtM 28/2021 is hereby cancelled

21st April 2022

P M Bailey
Deputy Harbour Master.
Harbour Office,
King's Lynn,
Norfolk PE30 ILL
T: 01553 773411
www.kingslynnport.co.uk